
## BL-RX810-L-LE



There are no specific service parts for BL-RX810-L-LE. BL-RX810-L service parts can be used for BL-RX810-L-LE.

DE-1770 TO-E Service parts can be used for DE-1770 TO-E-EE.			19	
ITEM NO.	SHIMANO CODE NO.	DESCRIPTION	INTERCHANGE- ABILITY	
1	Y0E198010	Left hand name plate L and fixing screw	A	
2	Y0E098030	Clamp band unit diameter (23.8 - 24.2 mm)	Α	
3	Y0C698030	Bleed screw and O-ring	Α	
4	Y0C598020	Left hand unit cover L and fixing screw	Α	
5	Y0JK98010	Bracket covers (pair)	Α	
6	Y0C514000	Joint support ring	Α	
7	Y8RD02000	Flange flare nut (M9/black)	Α	
* 8	Y13000090	TL-BR002 Funnel unit for M7 screw	Α	
9	Y0C598030	Left hand lid unit	Α	
10	Y0C698070	Lid fixing screw (3 pcs.) and lid spacer (2 pcs.)	Α	
11	Y0C578000	Diaphragm L	Α	

A: Same parts.

B: Parts are usable, but differ in materials, appearance, finish, size, etc.

Absence of mark indicates non-interchangeability.

Specifications are subject to change without notice.

Jun.-2022-4583C

 $\ensuremath{\text{\textcircled{O}}}$  Shimano Inc. I

